Date: User:

Monday, 7/9/2007 3:05:50 PM

Jason Murdoch

Process Sheet

Flocess offeet									
Customer		Dart Aerospace	Ltd.		Drawing Name	: D3628-1			
Job Number	: 33443								
Estimate Number	: 10804				5 441 1	: D36281			
P.O. Number	: NA	S.O. No. :	Jla		Part Number	: D30201 : RE-WORK			
This Issue Prsht Rev.	: 7/9/2007 : NC	5.U. NO. : 1	P#'		Drawing Number Project Number	: NIA			
First Issue	: 7/9/2007	Type :	SMALL/MED FAE	3	Drawing Revision	ACH:			
Previous Run	: 00015	.,,,,,			Material	: NIA			
Written By	; ':	\mathcal{L}			Due Date	: 7/16/2007	Qty:	1 Um:	Each
Checked & Approv	ed By $: \sum$								
Comment	:	•							
Additional Product									•
Job Number:									
Seq. #:	Machine O	r Operation:			Description :				
1.0	D36281	-		CUPPED	WASHER				
Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)									
	CUPPED								
	remove fro	m stock	•						
	B_35	095.							
0.0	Qty: 16	<u>196</u>	>	LIAND FIN	IISHING RESOURCE #1				
2.0	HAND FINISH			TAND FIN	ISTING RESOURCE #1				
Comme	ent: HAND FIN	IISHING RESOL	JRCE #1				- /-	_/.	
	strip off gr	ey powder coat.				PX	87/8°)///	
3.0	QC5			INSPECT	WORK TO CURRENT S	TEP	/	7	
Comme	ent: INSPECT	WORK TO CUR	RENT STEP	Ju	1. A.O. 11	196 cm	untect.		
4.0	PACKAGING 1			PACKAGI	NG RESOURCE #1				
Comme	ent: PACKAGI	NG RESOURCE	: #1						
	Identify wi	th part # , and or	riginal batch #.						
	Restock.						· L		
:	Location:_								
	Qty:			2/2	1/11	1/12 (1	96)	<i>;</i>	

Date:

Monday, 7/9/2007 3:05:50 PM

User:

Jason Murdoch

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D3628-1

Job Number: 33443

Part Number: D36281

Job Number:



Comment: FINAL INSPECTION/W/O RELEASE

Seq. #:

Machine Or Operation:

Description:

5.0

FINAL INSPECTION/W/O RELEASE

Job Completion



Destalia U 07-87-12